

Safety Instructions for Visitors & Externals

Welcome to our production facility in Dettingen! The safety and health of our employees, partners, and guests is our top priority. In our manufacturing facility, we handle heavy loads, work with thermal processes, and utilize state-of-the-art coating technologies.

Please carefully observe the following rules of conduct to minimize risks to yourself and others.

1. General Rules of Conduct & PPE
 - Personal Protective Equipment (PPE): Wearing safety shoes and safety glasses is mandatory throughout the entire production area.
 - Escort Requirement: Visitors may only enter the production areas when accompanied by an authorized person. The instructions of the escort must be followed at all times.
 - Prohibition of Substances: A strict ban on alcohol and drugs applies throughout the entire company premises. Smoking is only permitted in designated outdoor areas.
2. Caution: Forklift, Vehicle, and Crane Traffic
 - Caution, Logistics: Expect constant forklift and crane traffic throughout the entire plant.
 - Interaction: Always maintain eye contact with the operators before crossing their paths. Avoid abrupt changes of direction.
 - Suspended Loads: Walking through work areas under suspended crane loads is life-threatening and strictly prohibited. Maintain a generous safety distance.
3. Thermal Processes & Surfaces
 - Risk of Burns: Components in the thermal coating area can reach temperatures exceeding 200 °C. This heat is often not visible!
 - No Touching: Never touch freshly coated components or system parts. Maintain a safe distance from ovens and heating systems.
4. Machines, Crushing Hazards & Confidentiality
 - Mechanical Risks: Large, heavy, and moving components pose a significant risk of crushing and entrapment. Never reach into running processes or moving machine parts.
 - No Cameras & Confidentiality: Photography and filming are strictly prohibited. Customer-specific projects, drawings, and system layouts must be treated as absolutely confidential.
5. Emergency Procedures & First Aid
 - Escape- and Rescue Routes: Emergency exits are illuminated in green. Keep these routes and the fire extinguishers clear at all times.
 - Assembly Point: In case of evacuation (alarm sound), leave the building in an orderly fashion and assemble at the designated assembly point: area in front of the main entrance / parking lot Plant

Emergency Call & First Aid:

Ambulance / Fire Department: Landline: 0 – 112 or Mobile: 112 or use the emergency call function

Stay healthy! – Sincerely,
Management of Rudolf Gutbrod GmbH